Customer Owned Salesman Inspection

Manufacturer: CATERPILLAR Model: 140H Serial #: 2ZK08060

Year: 2003 Engine Serial #: Transmission Serial #:

SMU/Hrs: 12,000(APROX) Recommendation:

Last Scheduled System Last Preventative System Maintenance:

Notes:

MOTOR GRADERS CONFIGURATION

[X]EROPS [JOROPS [X]AIR CONDITIONER

[X]CAB, HIGH PROFIL []CAB, LOW PROFILE []PUSHBLOCK

[X]SIDE SHIFT []SNOW PLOW [X]SNOW WING (NOT INC)

[X]TIP CONTROL []VARIABLE HORSEPOWER []SCARIFIER, FRONT []RIPPER [X]DIFF LOCK/UNLOC []ACCUMULATORS

[]ALL WHEEL DRIVE []ANTI-THEFT SYSTEM []LIFT GROUP

[]PRODUCT LINK [X]SLIPCLUTCH []CE PLATE

GENERAL APPEARANCE

	N	VG	G	F	Р	NA	Remarks	Parts	Labor
	-	• •		Ŀ	Ŀ	IVA	Remarks	1 4113	Labor
Radiator Grill & Shroud	[]	[]	[X]	[]	[]	[]			
Eng. Enclose Hood / Stack	[]	[]	[X]	[]	[]	[]			
Fuel Tank	[]	[]	[X]	[]	[]	[]			
Crankcase Guard / Battery Box	[]	[]	[X]	[]	[]	[]	BATTERY BOXES REPAINTED		
Draw Bar	[]	[]	[X]	[]	[]	[]	SANDBLASTED		
Front Frame	[]	[]	[X]	[]	[]	[]	SANDBLASTED		
Rear Frame	[]	[]	[X]	[]	[]	[]	SANDBLASTED		
Bumper	[]	[]	[]	[]	[]	[X]			
Counterweight	[]	[]	[]	[]	[]	[]			
Pre-Cleaner Bowl	[]	[]	[X]	[]	[]	[]			
Cab or Canopy	[]	[]	[X]	[]	[]	[]			
Steps / Ladder	[]	[]	[X]	[]	[]	[]	RH OFF / AVAIL		
Grab Irons	[]	[]	[X]	[]	[]	[]			

Paint	[]	[]	[X]	[]	[]	[]		GOOD FOR AGE OF UNIT(MINOR RUST)				
Sheet Metal	[]	[]	[X]	[]	[]	[]						
						Condi	tion		Remarks	Par	ts	Labor
S.O.S. Taken		Υ	'es()			No	(X)	NA()				
Cleaning Required		Y	es(X)		N	D ()	NA ()	(CAB CLEAN)			
Notes												

SAFETY ITEMS

		Condition		Remarks	Parts	Labor
Rotating Beacon	Yes(X)	No ()	NA ()			
Signal Lights	Yes(X)	No ()	NA()			
ROPS	Yes(X)	No()	NA ()			

Condition: N=New VG=Very Good G=Good F=Fair P=Poor NA=Not Applicable

	Ν	y	G	F	Р	NA	Remarks	Parts	Labor
Horn	[]	[]	[X][]	[]	[]			
Notes									

GAUGES, OPERATOR STATION, CONSOLE

	N	VG	G	F	Р	NA	Remarks	Parts	Labor
Dash Console	[]	[]	[X]	[]	[]	[]			
Gauges	[]	[]	[X]	[]	[]	[]			
Switches	[]	[]	[X]	[]	[]	[]			
Heater	[]	[]	[X]	[]	[]	[]			
Seat Cushion / Arm Rest	[]	[]	[]	[X]	[]	[]	NO HOLES / SUSPENSION		
EMS Panel / Warnings	[]	[]	[X]	[]	[]	[]			
Door Latches	[]	[]	[X]	[]	[]	[]			
Glass/Mirrors	[]	[]	[]	[X]	[]	[]	FRONT RH&LH LWR CRACKED UPPER FRONT CHIPS & SCRATCH		
Air Conditioner	[]	[]	[X]	[]	[]	[]			

		Condition		Remarks	Parts	Labor
Current Safety Manual	Yes()	No(X)	NA ()			
Current O&MM	Yes()	No(X)	NA()			
Seat Belt	Yes(X)	No ()	NA()			
Back Up Alarm	Yes(X)	No ()	NA()			
Notes						

	Remarks	Parts	Labor
Fuel Level	70% AT APSL (SPARE WINTER UNIT)		

		Condition		Remarks	Parts	Labor
Oil Leaks	Yes(X)	No()	NA ()	GOV LEAKS @ FUEL PMP		
Blow By	Yes()	No(X)	NA ()			
Knocking	Yes()	No(X)	NA ()			
Water in Oil	Yes()	No(X)	NA ()			
Fluid Levels OK?	Yes(X)	No()	NA()			

	Remarks
Anti-Freeze Color	CAT LLC
Oil Pressure (H/L/N)	NORMAL
Smoke (B/D/L/W)	BLACK SMOKE @ START ONLY

Condition: N=New VG=Very Good G=Good F=Fair P=Poor NA=Not Applicable

	Ν	VG	G	F	Р	NA	Remarks	Parts	Labor
Air Cleaners	[]	[]	[X]	[]	[]	[]			
Exhaust / Muffler	[]	[]	[X]	[]	[]	[]			
Belts / Pulleys	[]	[]	[]	[X]	[]	[]	BUDGET REPLACE (SQUEALS)		
Notes									

COOLING SYSTEM

Condition: N=New VG=Very Good G=Good F=Fair P=Poor NA=Not Applicable

	N	VG	G	F	Р	NA	Remarks	Parts	Labor
Radiator	[]	[]	[X]] []	[]	[]			
Hoses	[]	[]	[X]] []	[]	[]			
Notes							_		_

		Condition		Remarks	Parts	Labor
Leaks	Yes()	No(X)	NA ()			

ELECTRICAL, STARTING AND CHARGING SYSTEM

	N	VG	G	F	Р	NA	Remarks	Parts	Labor
Batteries / Cables	[]	[]	[]	[X]	[]	[]	CRANKS OK @ OUTSIDE @ -12C		
Starter	[]	[]	[X]	[]	[]	[]	REPLACED		
Alternator	[]	[]	[X]	[]	[]	[]			

Wiring	[] [] [X] [] []	
Lighting	[] [] [X] [] [] BUDGET 2-3LIGHTS	
Notes		

		Condition		Remarks	Parts	Labor
Ether Aid	Yes(X)	No ()	NA ()			
Block Heater	Yes(X)	No ()	NA()			

TRANSMISSION

Condition: N=New **VG**=Very Good **G**=Good **F**=Fair **P**=Poor **NA**=Not Applicable

	N	VG	G	F	P	NA	Remarks	Parts	Labor
Transmission - Type	[]	[]	[X]	[]	[] []	SHIFTS / PULLS GOOD		
Case	[]	[]	[X]	[]]	[]			
Controls	[]	[]	[]	[X] [] []	CLUTCH APPEARS REQ ADJUST		
Seals	[]	[]	[X]	[]	[] []			
Torque Converter	[]	[]	[]	[]]] [X]			
Universal Joints	[]	[]	[X]	[]	[] []			
Lines / Fittings	[]	[]	[X]	[]	[] []			
Transmission - Reverse Shifts	[]	[]	[X]	[]]	[]			
Transmission - Forward Shifts	[]	[]	[X]	[]	[] []			

		Condition		Remarks	Parts	Labor
Transmission - Noisy	Yes()	No(X)	NA ()	Cold temp light @ start		
Leaks	Yes()	No(X)	NA()			
Notes						

STEERING

	N	VG	G	F	Р	NA	Remarks	Parts	Labor
Steering Linkage	[]	[]	[]	[x]	[]	[]			
Tie Rods / Rod Ends	[]	[]	[]	[x]	[]	[]			
Articulate P & B	[]	[]	[X]	[]	[]	[]	NO CLUNKS		
Steering Cylinder	[]	[]	[X]	[]	[]	[]	NO LEAKS		
Oil Lines	[]	[]	[]	[X]	[]	[]	SEVERAL BLISTERED HOSES MOST ORIGINAL		
Wheel Lean Cylinder	[]	[]	[X]	[]	[]	[]	NO LEAKS		
Supplemental Steer	[]	[]	[]	[]	[]	[X]			
Notes								•	·

Condition: N=New VG=Very Good G=Good F=Fair P=Poor NA=Not Applicable

	N	VG	G	F	Р	NA	Remarks	Parts	Labor
Lines	[]	[]	[X]	[]	[]	[]			
Accumulators	[]	[]	[]	[]	[]	[X]			
Parking Brake	[]	[]	[X]	[]	[]	[]			
Notes				В	RAK	ES AP	PEAR WEAK WHEN TESTED. G	OOD AIR PRESSUF	RE
	_								

		Condition		Remarks	Parts	Labor
Leaks	Yes()	No(X)	NA ()			

	Remarks
Holding What Gear?	ALL GEARS 1 TO 8STALLED OUT IN 4R

TANDEMS

Condition: N=New VG=Very Good G=Good F=Fair P=Poor NA=Not Applicable

	N	VG	G	ì	F	Р	NA	Remarks	Parts	Labor
Tandems	[]	[]	[X]	[]	[]	[]	NO LEAKS		
Wheel Lugs & Rims	[]	[]	[X]	[]	[]	[]			
Differential	[]	[]	[X]	[]	[]	[]			

HYDRAULICS

	N	VG	G	F	Р	NA	Remarks	Parts	Labor
Operating Condition	[]	[]	[X]	[]	[]	[]	SLOW @ COLD START		
Tank	[]	[]	[X]	[]	[]	[]			
Pumps & Valves	[]	[]	[]	[X]	[]	[]	NOISE @ COLD (MINOR)		
Hose Lines	[]	[]	[]	[X]	[]	[]	SEVERAL BLISTERED HOSES		
Linkage	[]	[]	[X]	[]	[]	[]			
Side Shift Cylinder	[]	[]	[X]	[]	[]	[]	NO LEAKS ON HYD CYLS		
Lift Cylinders	[]	[]	[X]	[]	[]	[]			
Tip Cylinder	[]	[]	[X]	[]	[]	[]			
Wheel Lean Cylinder	[]	[]	[x]	[]	[]	[]			
Circle, Shoes & Plates	[]	[]	[X]	[]	[]	[]	REQUIRES FULL ADJUSTMENT & WEAR PARTS		

Circle Side Shift Cylinder	[]		[X]	[]	[]	[]					
Scar. Lift Arms & Gear Box	[]	[]	[]	[]	[]	[x]					
Ripper/Scar. Lift Cylinder	[]	[]	[]	[]	[]	[x]					
Drive Line	[]	[]	[x]	[]	[]	[]					
Notes											
						nditi	n .	Domarko	Parte	1.6	hor

		Condition		Remarks	Parts	Labor
Leaks	Yes()	No(x)	NA ()			

BLADE

Condition: N=New VG=Very Good G=Good F=Fair P=Poor NA=Not Applicable

				• •			10 10., 0000 0 0000 1 10 1 100. 10.1.	017 ipp00.0.0		
	N	VG	G	F	Р	NA	Remarks	Parts	Labor	
Face / Moldboard	[]	[]	[]	[X]	[]	[]	FACE GOOD/ FROG OK			
Cutting Edge Condition	[]	[]	[]	[X]	[]	[]	BUDGET NEW			
Notes										
		Remarks								
Blade Size							14FT X 27 INCH C/W 2FT LH EXTENTION			

RIPPER (NO RIPPER)

Condition: N=New VG=Very Good G=Good F=Fair P=Poor NA=Not Applicable

	N	VG	G	F	=	Ρ	NA	Remarks	Parts	Labor
Pins & Bushings	[]	[]	[]] []	[]	[]			
Beam / Frame	[]	[]	[]] []	[]	[]			
Shanks / GET	[]	[]	[]] []	[]	[]			
Lines / Fittings	[]	[]	[] []	[]	[]			

SCARIFER (NO SCARIFIER)

Condition: N=New **VG**=Very Good **G**=Good **F**=Fair **P**=Poor **NA**=Not Applicable

	Ν	VG	G	F	Р	NA	Remarks	Parts	Labor
Pins & Bushings	[]	[]	[]	[]] []	[]			
Brackets / Studs	[]	[]	[]	[]][:	[]			
Beam / Frame	[]	[]	[]	[]][:	[]			
Shanks / GET	[]	[]	[]	[]][:	[]			
Lines / Fittings	[]	[]	[]	[]] []	[]			

SNOW WING (CRAIG 301-12 1998) MAY NOT BE INCLUDED

Condition: N=New VG=Very Good G=Good F=Fair P=Poor NA=Not Applicable

	N	VG	G	F	Р	NA	Remarks	Parts	Labor
Operating Condition	[]	[]	[]	[X]	[]	[]			
Cylinder Condition	[]	[]	[]	[X]	[]	[]			
Rear Post	[]	[]	[]	[X]	[]	[]			
Moldboard	[]	[]	[]	[X]	[]	[]	SMALL TOP DENTS		

TIRES

	Make / Serial#	Tread Depth in 1/32"	% Life Remaining	F	Recappe	d	Tread	Cuts/Cl	nunks	Side	Side Cuts Section		
Right Front	MICHELIN	SNOPLUS	25%	Yes()	No(X)	NA ()	Yes()	No(X)	NA ()	Yes()	No(x)	NA ()	
Right Rear Center	<i></i>	6637 6637	20%	Yes()	No(X)	NA()	Yes()	No(X)	NA()	Yes()	No(X)	NA()	
Right Rear	un un	un un	25%	Yes()	No(X)	NA ()	Yes()	No(X)	NA()	Yes()	No(X)	NA ()	
Left Front	un un	un un	35%	Yes()	No(X)	NA ()	Yes(X)	No()	NA ()	Yes()	No(X)	NA ()	
Left Rear Center	un un	un un	25%	Yes()	No(X)	NA ()	Yes()	No(X)	NA ()	Yes()	No(X)	NA ()	
Left Rear	un un	un un	20%	Yes()	No(X)	NA ()	Yes()	No(X)	NA()	Yes()	No(X)	NA ()	
Tire Size					17.5 X	25							
Average Life Remaining		25%											
Notes	NO CUTS NO MAJOR TOP OR SIDE CRACKS. RH-F-UNEVEN.												
		Cond	ition			Re	marks		Parts	3	Lab	or	

		Condition		Remarks	Parts	Labor
Spare	Yes()	No(X)	NA()			

	Remarks
Number of Chains	
Chains Type (Cross Barr, Mesh)	
% Remaining on Chains	

COMMENTS, MISC. REPAIRS, GENERAL REMARKS

Remarks	Parts	Labor
HOUR METER NOT WORKINGRECORDED JAN 2017 @ 11,400 HOURS. 12,000 ESTIMATED NOW.		
140H POWERTRAIN APPEARS IN SOUND CONDITION		
ORIGINAL ENGINE & REBUILT TRANS IN 2010		
GRADER IS CLEAN, WELL MAINTAINED, MINOR RUST, GOOD APPEARANCE.		
ORIGINAL OWNER RM316 WITH NO WINTER USE		