

**1994 CATERPILLAR 320L****TRACK EXCAVATORS**

Serial #: 9KK01210

SMU/Hrs: 12567

**Client**

---

**Features**

---

COUPLER, QUICK

**Condition**

---

**GENERAL APPEARANCE**

	Condition - Remarks	Parts	Labor	Approved?	Photos
Radiator Grill & Shroud	Fair				
Eng. Enclose Hood / Stack	Fair				
Fuel Tank	Good				
Crankcase Guard / Battery Box	Fair				
Draw Bar	Good				
Main Frame Welds	Good				
Car Body	Good				
Bumper	Good				
Counterweight	Good				
Steps / Ladder	Poor				
Grab Irons	Poor				

Paint	Fair				
Engine Doors	Poor				
	<b>Condition - Remarks</b>	<b>Parts</b>	<b>Labor</b>	<b>Approved?</b>	<b>Photos</b>
S.O.S. Taken	No				
Cleaning Required	Yes				

### SAFETY ITEMS

	<b>Condition - Remarks</b>	<b>Parts</b>	<b>Labor</b>	<b>Approved?</b>	<b>Photos</b>
Cab Guards	No				
	<b>Condition - Remarks</b>	<b>Parts</b>	<b>Labor</b>	<b>Approved?</b>	<b>Photos</b>
Horn	Good				
Brake Hold	Good				
Swing Brake	Good				

### GAUGES, OPERATOR STATION, CONSOLE

	<b>Condition - Remarks</b>	<b>Parts</b>	<b>Labor</b>	<b>Approved?</b>	<b>Photos</b>
Gauges	Fair				
Switches	Poor				
Door Latches	Fair				
Meter	Good				
Seat Cushion / Arm Rest	Fair				
EMS Panel / Warnings	Poor				
Glass/Mirrors	Poor				
	<b>Condition - Remarks</b>	<b>Parts</b>	<b>Labor</b>	<b>Approved?</b>	<b>Photos</b>
Current Safety	No				

<b>Manual</b>					
<b>Current O&amp;MM</b>	No				
<b>Back Up Alarm</b>	No				

## ENGINE

	Condition - Remarks	Parts	Labor	Approved?	Photos
<b>Oil Leaks</b>	Yes - valve cover?				
<b>Blow By</b>	No				
<b>Knocking</b>	No				
<b>Water in Oil</b>	No				
<b>Fluid Levels OK?</b>	Yes				
	Condition - Remarks	Parts	Labor	Approved?	Photos
<b>Belts / Pulleys</b>	Good				
<b>Exhaust / Muffler</b>	Good				

## COOLING SYSTEM

	Condition - Remarks	Parts	Labor	Approved?	Photos
<b>Hoses</b>	Good				
<b>Radiator</b>	Good				
	Condition - Remarks	Parts	Labor	Approved?	Photos
<b>Leaks</b>	No				

## ELECTRICAL, STARTING AND CHARGING SYSTEM

	Condition - Remarks	Parts	Labor	Approved?	Photos
<b>Batteries / Cables</b>	Fair				
<b>Starter</b>	Good				

Alternator	Good				
Wiring	Fair				
Lighting	Poor				
	<b>Condition - Remarks</b>	<b>Parts</b>	<b>Labor</b>	<b>Approved?</b>	<b>Photos</b>
Ether Aid	No				
Block Heater	No				

### HYDRAULICS

	Condition - Remarks	Parts	Labor	Approved?	Photos
Pump Drive	Good				
Pumps & Valves	Good				
Boom Cylinder	Good				
Bucket Cylinder	Good				
Stick Cylinder	Good				
Hose Lines	Fair				
Control Linkage	Good				
Swing Gear	Good				
Tank	Fair				
Travel Motors	Good				
Notes	hyd oil low				
	Condition - Remarks	Parts	Labor	Approved?	Photos
Swing Drive Oil Level	ok				

### BOOM

	Condition - Remarks	Parts	Labor	Approved?	Photos
--	---------------------	-------	-------	-----------	--------

Pins & Bushings	Fair				
Boom Condition	Fair				

### STICK

	Condition - Remarks	Parts	Labor	Approved?	Photos
Pins & Bushings	Fair				
Stick Conditions	Fair				

### BUCKET

	Condition - Remarks	Parts	Labor	Approved?	Photos
Cutting Edges	Fair				
Teeth / Adapters	Fair				
Bucket Bottom	Fair				
Bucket Sides	Fair				
Bucket Linkage	Fair				
	Condition - Remarks	Parts	Labor	Approved?	Photos
Quick Coupler	Yes - WERK BRAU				

### UNDERCARRIAGE

	Condition - Remarks	Parts	Labor	Approved?	Photos
Track Frame - Left	Good				
Track Frame - Right	Good				
	Condition - Remarks	Parts	Labor	Approved?	Photos
Pins & Bushings Turned?	No				