

Unit #: D808
EIN #: ED6W98

Machine: D8R Sii Year: 2003 Serial #: AKA00778
Eng. Serial #: BET04578
Donaldson Fleetguard Original Transmission #: HRC01097

Filters:

Oil Filter LF3566 1R-1808 Slope No
Fuel Filter Pri P551010 Rippers 2
Fuel Filter Sec P551311 FF5319 1R-0749 Ripper Pins 6Y-3394 \$10.97
Hyd Tank Filter P550523 HF7376 IR-0735/ 139-1537 Cleanout Ripper Ret: 8E-4743 \$11.33
Hyd Pilot filter P165332 HF6551 102-2828 Shank Prot: 8E-1848
Trans, Outer | P165239 132-8876
Torque Filter, Closest to (1R-0778 Do not use P165239 in this housing.
Trans Filter O 5P-3620 \$6.32

Air Inner P532506 AF25136M Edges;
Air Outter P532505 AF25135M Center 7T-9126
Ends 7T-9125
Batteries (4) (3T-5760 Corner Bits 8E-4193/4194
Cab A/C Filter 6T-5068 Bolts (33) 1" x 3.00"
Cab A/C Filter P527595 AF26181 6T-0988

Fan Belt Banc 216-4326 \$107.48
A/C Belts 2S-9506 \$20.84
Alt Belt (1" sh 6N-6657 \$26.13
Drive Sprocket Finals are drilled for updated Cat Sprockets. 314-5462 x5.
Starter (50M) Replaced with rebuilt one 10/28/15 Russ.
Alternator New 2/4/17 Frank. Takes the big one.
Service Information:

Date:	Hours:	Service:	Mechanic:	Comments:
6/30/2007	3884	1000	Frank	
2/23/2008	4413	1500	craig	
4/15/2008	4649	2000	Craig	In Shop.
	4904	250?	??	
9/17/2008	5124	250	Craig	RS 3rd roller from back leaking.
12/17/2008	5366	500	Craig	Heater valve leaking.
2/21/2009	5594	750	craig	Needs rain cap.
6/8/2009	5844	1000	craig	Replaced all leaking hoses around torque.
11/9/2009	6104	250	craig	250 at San Antonio Dam.
3/31/2010	6360	500	craig	500 at Carmuese.
6/18/2010	6616	250	craig	250 in shop. New edges.
10/25/2010	6812	2000	Frank	
7/13/2011	7022	250	Frank	
2/13/2012	7236	500	?	
5/24/2012	7446	750	Jim	750 at Quest Dam job.
7/10/2012	7720	1000	Jim	Rebuilt Seat Suspension.

9/11/2012	8103	1250	Jim	133 hrs overdue at Quest.
3/20/2013	8429	1500	Frank	76 hrs overdue.
5/6/2013	8535	*****	Chris	Changed hyd oil and filters.
6/19/2013	8348	1750	Jim	750 at Recon, Fillmore, Removed sand grid.
9/12/2013	8979	2000	Jim	2000 at Recon Fillmore, 83 hrs overdue. Changed finals at
10/31/2013	9175	*****	Frank	Changed hyd oil and filters.
11/20/2013	9265	250	Jim	Oil Pan leaking on LS.
4/5/2014	9739	500	Alex	224 hrs overdue for PM
6/16/2014	9983	250	Frank	Track Guides and rollers worn
9/10/2014	10262	1000	Frank	Replaced A/C belt. Changed Hyd oil due to dirty sample.
11/25/2014	10482	1250	Jim	
3/18/2015	10749	1500	Jim	U/C Worn out.
6/26/2015	11024	1750	Dave	Performed In-Frame rebuild on engine, New U/C.
10/2/2015	11236	2000	Jim	Needs Trans Filter Housing.
11/25/2015	11492	250	Jim	Found plastic in primary fuel filter.
1/22/2016	11574	250	Daniel	Charles replaced aftercooler WP, new engine bearings.
6/28/2016	11997	500	Gerry	173 hrs overdue.
10/12/2016	12203	750	Daniel	Flipped edges, new Corners.
5/5/2017	12616	1000	Frank	163 hrs overdue. Rebuilt Fuse panel.

nd trans.