

SPECIFICATIONS

1992 CATERPILLAR 140G

Customer Owned Salesman Inspection

MOTOR GRADERS

Inspection Number:	Serial #:	72V14775
Date Created:	Engine Serial #:	N/A
Last Updated:	Transmission Serial #:	N/A
Originated By:	SMU/Hrs:	9833
Inspector:	Last Scheduled Oil Sample:	N/A
Reviewer:	Last Cat Track System Inspection:	N/A
Salesman:	Last Preventative Maintenance:	N/A
Location:	Recommendation:	no recommendation
Asking Price:	Final Price:	N/A

Client

Name: State:
Client Id: Country:
Company:

Features

- EROPS
- AIR CONDITIONER
- CAB, LOW PROFILE
- SIDE SHIFT
- SNOW WING
- VARIABLE HORSEPOWER
- DIFF LOCK/UNLOC
- ENGINE ENCLOSURES
- LIFT GROUP
- SLIPCLUTCH
- LIGHTING
- BLADE FLOAT

Condition

GENERAL APPEARANCE

	Condition - Remarks	Parts	Labor	Approved?	Photos
Radiator Grill & Shroud	Fair			<input type="checkbox"/>	
Eng. Enclose Hood / Stack	Good			<input type="checkbox"/>	
Fuel Tank	Good			<input type="checkbox"/>	
Crankcase Guard / Battery Box	Good			<input type="checkbox"/>	
Draw Bar	Good			<input type="checkbox"/>	
Front Frame	Good			<input type="checkbox"/>	
Rear Frame	Good			<input type="checkbox"/>	
Bumper	Good			<input type="checkbox"/>	

Pre-Cleaner Bowl	Good			<input type="checkbox"/>	
Cab or Canopy	Good			<input type="checkbox"/>	
Steps / Ladder	Good			<input type="checkbox"/>	
Grab Irons	Good			<input type="checkbox"/>	
Paint	Fair			<input type="checkbox"/>	
Sheet Metal	Good			<input type="checkbox"/>	

	Condition - Remarks	Parts	Labor	Approved?	Photos
S.O.S. Taken	No			<input type="checkbox"/>	
Cleaning Required	No			<input type="checkbox"/>	

SAFETY ITEMS

	Condition - Remarks	Parts	Labor	Approved?	Photos
Rotating Beacon	Yes			<input type="checkbox"/>	
Signal Lights	Yes			<input type="checkbox"/>	
ROPS	Yes			<input type="checkbox"/>	

	Condition - Remarks	Parts	Labor	Approved?	Photos
Horn	Good			<input type="checkbox"/>	

GAUGES, OPERATOR STATION, CONSOLE

	Condition - Remarks	Parts	Labor	Approved?	Photos
Dash Console	Good			<input type="checkbox"/>	
Gauges	Good			<input type="checkbox"/>	
Switches	Good			<input type="checkbox"/>	
Heater	Good			<input type="checkbox"/>	
Seat Cushion / Arm Rest	Good			<input type="checkbox"/>	
EMS Panel / Warnings	Good			<input type="checkbox"/>	
Door Latches	Good			<input type="checkbox"/>	
Glass/Mirrors	Good			<input type="checkbox"/>	
Air Conditioner	Good			<input type="checkbox"/>	

	Condition - Remarks	Parts	Labor	Approved?	Photos
Current Safety Manual	No			<input type="checkbox"/>	
Current O&MM	No			<input type="checkbox"/>	
Seat Belt	Yes			<input type="checkbox"/>	
Back Up Alarm	Yes			<input type="checkbox"/>	

ENGINE

	Condition - Remarks	Parts	Labor	Approved?	Photos
Oil Leaks	Yes - FUEL INJECTOR SEAL IS STARTING TO LEAK OIL (DAMP NOT DRIPPING)			<input type="checkbox"/>	
Blow By	Yes - MODERATE			<input type="checkbox"/>	
Knocking	No			<input type="checkbox"/>	
Water in Oil	No			<input type="checkbox"/>	
Fluid Levels OK?	Yes			<input type="checkbox"/>	

	Condition - Remarks	Parts	Labor	Approved?	Photos
Anti-Freeze Color	NORMAL			<input type="checkbox"/>	
Oil Pressure (H/L/N)	NORMAL			<input type="checkbox"/>	
Smoke (B/D/L/W)	NORMAL			<input type="checkbox"/>	

	Condition - Remarks	Parts	Labor	Approved?	Photos
Air Cleaners	Good			<input type="checkbox"/>	
Exhaust / Muffler	Good			<input type="checkbox"/>	
Belts / Pulleys	Good			<input type="checkbox"/>	
Notes	ENGINE SOUNDS GOOD				

————— COOLING SYSTEM —————

	Condition - Remarks	Parts	Labor	Approved?	Photos
Radiator	Good			<input type="checkbox"/>	
Hoses	Good			<input type="checkbox"/>	
Notes	COOLS NORMAL				

	Condition - Remarks	Parts	Labor	Approved?	Photos
Leaks	No			<input type="checkbox"/>	

————— ELECTRICAL, STARTING AND CHARGING SYSTEM —————

	Condition - Remarks	Parts	Labor	Approved?	Photos
Batteries / Cables	Good			<input type="checkbox"/>	
Starter	Good			<input type="checkbox"/>	
Alternator	Good			<input type="checkbox"/>	
Wiring	Good			<input type="checkbox"/>	
Lighting	Good			<input type="checkbox"/>	

	Condition - Remarks	Parts	Labor	Approved?	Photos
Ether Aid	No			<input type="checkbox"/>	
Block Heater	Yes			<input type="checkbox"/>	

————— TRANSMISSION —————

	Condition - Remarks	Parts	Labor	Approved?	Photos

Transmission - Type	Good			<input type="checkbox"/>	
Case	Good			<input type="checkbox"/>	
Controls	Good			<input type="checkbox"/>	
Seals	Good			<input type="checkbox"/>	
Torque Converter	Good			<input type="checkbox"/>	
Universal Joints	Good			<input type="checkbox"/>	
Lines / Fittings	Good			<input type="checkbox"/>	
Transmission - Reverse Shifts	Good			<input type="checkbox"/>	
Transmission - Forward Shifts	Good			<input type="checkbox"/>	

	Condition - Remarks	Parts	Labor	Approved?	Photos
Transmission - Noisy	No			<input type="checkbox"/>	
Leaks	No			<input type="checkbox"/>	
Notes	TRANSMISSION SHIFTS NORMAL				

STEERING

	Condition - Remarks	Parts	Labor	Approved?	Photos
Steering Linkage	Good			<input type="checkbox"/>	
Tie Rods / Rod Ends	Good			<input type="checkbox"/>	
Articulate P & B	Good			<input type="checkbox"/>	
Steering Cylinder	Good			<input type="checkbox"/>	
Oil Lines	Good			<input type="checkbox"/>	
Wheel Lean Cylinder	Good			<input type="checkbox"/>	
Supplemental Steer	Good			<input type="checkbox"/>	
Notes	STEERING FUNCTIONS NORMAL				

BRAKE

	Condition - Remarks	Parts	Labor	Approved?	Photos
Lines	Good			<input type="checkbox"/>	
Accumulators	Good			<input type="checkbox"/>	
Parking Brake	Good			<input type="checkbox"/>	
Notes	BRAKES ARE FUNCTIONAL				

	Condition - Remarks	Parts	Labor	Approved?	Photos
Leaks	No			<input type="checkbox"/>	

TANDEMS

	Condition - Remarks	Parts	Labor	Approved?	Photos
Tandems	Good			<input type="checkbox"/>	

Wheel Lugs & Rims	Good			<input type="checkbox"/>	
Differential	Good			<input type="checkbox"/>	

HYDRAULICS

	Condition - Remarks	Parts	Labor	Approved?	Photos
Overall Operating Condition	Good			<input type="checkbox"/>	
Tank	Good			<input type="checkbox"/>	
Pumps & Valves	Good			<input type="checkbox"/>	
Hose Lines	Good			<input type="checkbox"/>	
Linkage	Good			<input type="checkbox"/>	
Side Shift Cylinder	Good			<input type="checkbox"/>	
Lift Cylinders	Good			<input type="checkbox"/>	
Tip Cylinder	Good			<input type="checkbox"/>	
Wheel Lean Cylinder	Good			<input type="checkbox"/>	
Circle, Shoes & Plates	Good			<input type="checkbox"/>	
Circle Side Shift Cylinder	Fair - STARTING TO GET DAMP			<input type="checkbox"/>	
Scar. Lift Arms & Gear Box	Good			<input type="checkbox"/>	
Ripper/Scar. Lift Cylinder	Good			<input type="checkbox"/>	
Drive Line	Good			<input type="checkbox"/>	
Notes	HYDRAULICS ARE FUNCTIONAL				

	Condition - Remarks	Parts	Labor	Approved?	Photos
Leaks	No			<input type="checkbox"/>	

BLADE

	Condition - Remarks	Parts	Labor	Approved?	Photos
Face / Moldboard	Good			<input type="checkbox"/>	
Cutting Edge Condition	New			<input type="checkbox"/>	
Notes	CUTTING EDGES ARE NEW				

	Condition - Remarks	Parts	Labor	Approved?	Photos
Blade Size	14' WITH 2' EXT. L.H.			<input type="checkbox"/>	

SNOW WING

	Condition - Remarks	Parts	Labor	Approved?	Photos
Operating Condition	Good			<input type="checkbox"/>	
Cylinder Condition	Good			<input type="checkbox"/>	
Rear Post	Good			<input type="checkbox"/>	

Moldboard	Good - 12' BALDERSON			<input type="checkbox"/>	
-----------	----------------------	--	--	--------------------------	--

————— TIRES —————

	Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section	Photos
Right Front	MICHELIN		70	No	No	No	
Right Rear Center	MICHELIN		70	No	No	No	
Right Rear	MICHELIN		70	No	No	No	
Left Front	MICHELIN		70	No	No	No	
Left Rear Center	MICHELIN		70	No	No	No	
Left Rear	MICHELIN		70	No	No	No	
Tire Size	14.00R24 Michelin Sno Plus						
Average Life Remaining	70						

	Condition - Remarks	Parts	Labor	Approved?	Photos
Spare	No			<input type="checkbox"/>	

————— COMMENTS, MISC. REPAIRS, GENERAL REMARKS —————

	Parts	Labor	Approved?	Photos
Machine is in good shape runs good for its age. Newer tires, well kept machine. No major issues, very few leaks.			<input type="checkbox"/>	