

SPECIFICATIONS

1988 CHAMPION 720A		Customer Owned Salesman Inspection	
MOTOR GRADERS			
Inspection Number:	Serial #:	187-458-18675-88	
Date Created:	Engine Serial #:	N/A	
Last Updated:	Transmission Serial #:	N/A	
Originated By:	SMU/Hrs:	12434	
Inspector:	Last Scheduled Oil Sample:	N/A	
Reviewer:	Last Cat Track System Inspection:	N/A	
Salesman:	Last Preventative Maintenance:	N/A	
Location:	Recommendation:		
Asking Price:	Final Price:	N/A	

Description

Tall cab, 12' x 24" moldboard, good glass, good lights, one fan works, no a/c, blower works. Seat cushion is ok. Good running. Good recap tires.

Features

- EROPS
- AIR CONDITIONER
- CAB, HIGH PROFILE
- SIDE SHIFT
- TIP CONTROL
- DIFF LOCK/UNLOC
- LIFT GROUP
- LIGHTING

Condition

GENERAL APPEARANCE

	Condition - Remarks	Parts	Labor	Approved?	Photos
Radiator Grill & Shroud	Good			<input type="checkbox"/>	
Eng. Enclose Hood / Stack	Good			<input type="checkbox"/>	
Fuel Tank	Good			<input type="checkbox"/>	
Crankcase Guard / Battery Box	Good			<input type="checkbox"/>	
Draw Bar	Good			<input type="checkbox"/>	

Front Frame	Good			<input type="checkbox"/>	
Rear Frame	Good			<input type="checkbox"/>	
Bumper	Good			<input type="checkbox"/>	
Cab or Canopy	Good			<input type="checkbox"/>	
Steps / Ladder	Fair			<input type="checkbox"/>	
Grab Irons	Good			<input type="checkbox"/>	
Paint	Poor			<input type="checkbox"/>	
Sheet Metal	Good			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
S.O.S. Taken	No			<input type="checkbox"/>	
Cleaning Required	No			<input type="checkbox"/>	
Notes					

.SAFETY ITEMS.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Rotating Beacon	No			<input type="checkbox"/>	
Signal Lights	Yes			<input type="checkbox"/>	
ROPS	Yes			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
Horn	Good			<input type="checkbox"/>	
Notes					

.GAUGES, OPERATOR STATION, CONSOLE.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Dash Console	Good			<input type="checkbox"/>	

Gauges	Good			<input type="checkbox"/>	
Switches	Good			<input type="checkbox"/>	
Heater	Good			<input type="checkbox"/>	
Seat Cushion / Arm Rest	Good			<input type="checkbox"/>	
EMS Panel / Warnings	Good			<input type="checkbox"/>	
Door Latches	Fair			<input type="checkbox"/>	
Glass/Mirrors	Good			<input type="checkbox"/>	
Air Conditioner	Poor			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
Current Safety Manual	Yes			<input type="checkbox"/>	
Current O&MM	No			<input type="checkbox"/>	
Seat Belt	Yes			<input type="checkbox"/>	
Back Up Alarm	No			<input type="checkbox"/>	
Notes					

.ENGINE.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Oil Leaks	Yes			<input type="checkbox"/>	
Blow By	No			<input type="checkbox"/>	
Knocking	No			<input type="checkbox"/>	
Water in Oil	No			<input type="checkbox"/>	
Fluid Levels OK?	Yes			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
Air Cleaners	Fair			<input type="checkbox"/>	

Exhaust / Muffler	Good			<input type="checkbox"/>	
Belts / Pulleys	Good			<input type="checkbox"/>	
Notes					

.COOLING SYSTEM.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Radiator	Good			<input type="checkbox"/>	
Hoses	Good			<input type="checkbox"/>	
Notes					
	Condition - Remarks	Parts	Labor	Approved?	Photos
Leaks	No			<input type="checkbox"/>	

.ELECTRICAL, STARTING AND CHARGING SYSTEM.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Batteries / Cables	Good			<input type="checkbox"/>	
Starter	Good			<input type="checkbox"/>	
Alternator	Good			<input type="checkbox"/>	
Wiring	Good			<input type="checkbox"/>	
Lighting	Good			<input type="checkbox"/>	
Notes					
	Condition - Remarks	Parts	Labor	Approved?	Photos
Ether Aid	No			<input type="checkbox"/>	

.TRANSMISSION.

	Condition - Remarks	Parts	Labor	Approved?	Photos

Transmission - Type	Good			<input type="checkbox"/>	
Case	Good			<input type="checkbox"/>	
Controls	Good			<input type="checkbox"/>	
Seals	Good			<input type="checkbox"/>	
Torque Converter	Good			<input type="checkbox"/>	
Universal Joints	Good			<input type="checkbox"/>	
Lines / Fittings	Good			<input type="checkbox"/>	
Transmission - Reverse Shifts	Good			<input type="checkbox"/>	
Transmission - Forward Shifts	Good - A little clunky between gears, but shifts fine.			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
Transmission - Noisy	No			<input type="checkbox"/>	
Leaks	No			<input type="checkbox"/>	
Notes					

.STEERING.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Steering Linkage	Good			<input type="checkbox"/>	
Tie Rods / Rod Ends	Good			<input type="checkbox"/>	
Articulate P & B	Good			<input type="checkbox"/>	
Steering Cylinder	Good			<input type="checkbox"/>	
Oil Lines	Good			<input type="checkbox"/>	
Wheel Lean Cylinder	Good			<input type="checkbox"/>	

Supplemental Steer	Good			<input type="checkbox"/>	
Notes					

.BRAKE.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Lines	Good			<input type="checkbox"/>	
Accumulators	Good			<input type="checkbox"/>	
Parking Brake	Good			<input type="checkbox"/>	
Notes					
	Condition - Remarks	Parts	Labor	Approved?	Photos
Leaks	No			<input type="checkbox"/>	

.TANDEMS.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Tandems	Good			<input type="checkbox"/>	
Wheel Lugs & Rims	Good			<input type="checkbox"/>	
Differential	Good			<input type="checkbox"/>	

.HYDRAULICS.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Overall Operating Condition	Good			<input type="checkbox"/>	
Tank	Good			<input type="checkbox"/>	
Pumps & Valves	Good			<input type="checkbox"/>	
Hose Lines	Good			<input type="checkbox"/>	

Linkage	Good			<input type="checkbox"/>	
Side Shift Cylinder	Good			<input type="checkbox"/>	
Lift Cylinders	Good			<input type="checkbox"/>	
Tip Cylinder	Good			<input type="checkbox"/>	
Wheel Lean Cylinder	Fair - Drifts after a while.			<input type="checkbox"/>	
Circle, Shoes & Plates	Good			<input type="checkbox"/>	
Circle Side Shift Cylinder	Good			<input type="checkbox"/>	
Drive Line	Good			<input type="checkbox"/>	
Notes					
	Condition - Remarks	Parts	Labor	Approved?	Photos
Leaks	No			<input type="checkbox"/>	

.BLADE.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Face / Moldboard	Good			<input type="checkbox"/>	
Cutting Edge Condition	Good			<input type="checkbox"/>	
Notes					
	Condition - Remarks	Parts	Labor	Approved?	Photos
Blade Size	14' x 24"			<input type="checkbox"/>	

.TIRES.

	Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section	Photos
--	-----------------------	-----------------------------	-------------------------	-----------------	--------------------------	--------------------------	---------------

Right Front	14.00R24 Mich Sno		70	Yes	No	No	
Right Rear Center	14.00R24 Mich Sno		70	Yes	No	No	
Right Rear	14.00R24 Mich Sno		70	Yes	No	No	
Left Front	14.00R24 Mich Sno		70	Yes	No	No	
Left Rear Center	14.00R24 Mich Sno		70	Yes	No	No	
Tire Size							
Average Life Remaining	70						
Notes							
	Condition - Remarks			Parts	Labor	Approved?	Photos
Spare	No					<input type="checkbox"/>	