

SPECIFICATIONS**2001 CATERPILLAR 140HNA****Customer Owned Certified****MOTOR GRADERS**

Inspection Number:	Serial #:	2ZK05986
Date Created:	Engine Serial #:	6NC25010
Last Updated:	Transmission Serial #:	4MY10067
Originated By:	SMU/Hrs:	12245
Inspector:	Last Scheduled Oil Sample:	N/A
Reviewer:	Last Cat Track System Inspection:	N/A
Salesman:	Last Preventative Maintenance:	N/A
Location:	Recommendation:	no recommendation
Asking Price:	Final Price:	N/A

Features

- EROPS
- AIR CONDITIONER
- CAB, LOW PROFILE
- SIDE SHIFT
- TIP CONTROL
- VARIABLE HORSEPOWER
- DIFF LOCK/UNLOC
- LIFT GROUP

Condition**GENERAL APPEARANCE**

	Condition - Remarks	Parts	Labor	Approved?	Photos
Radiator Grill & Shroud	Very Good			<input type="checkbox"/>	
Eng. Enclose Hood / Stack	Very Good - Right side door stiff			<input type="checkbox"/>	
Fuel Tank	Very Good			<input type="checkbox"/>	
Crankcase Guard / Battery Box	Very Good			<input type="checkbox"/>	
Front Frame	Very Good			<input type="checkbox"/>	
Rear Frame	Very Good			<input type="checkbox"/>	

Bumper	Very Good			<input type="checkbox"/>	
Pre-Cleaner Bowl	Very Good			<input type="checkbox"/>	
Cab or Canopy	Very Good			<input type="checkbox"/>	
Steps / Ladder	Very Good			<input type="checkbox"/>	
Grab Irons	Very Good			<input type="checkbox"/>	
Paint	Very Good			<input type="checkbox"/>	
Sheet Metal	Very Good			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
S.O.S. Taken	Yes			<input type="checkbox"/>	
Cleaning Required	Yes			<input type="checkbox"/>	

.SAFETY ITEMS.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Safety Decals In Place	Yes			<input type="checkbox"/>	
Safety Decals Legible	Yes			<input type="checkbox"/>	
Rotating Beacon	Yes			<input type="checkbox"/>	
Signal Lights	Yes			<input type="checkbox"/>	
ROPS	Yes			<input type="checkbox"/>	
Warning Lights	Yes			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
Horn	Poor - trys to make noise, cap broken			<input type="checkbox"/>	

.GAUGES, OPERATOR STATION, CONSOLE.

	Condition - Remarks	Parts	Labor	Approved?	Photos
--	---------------------	-------	-------	-----------	--------

Dash Console	Good			<input type="checkbox"/>	
Gauges	Good			<input type="checkbox"/>	
Switches	Good			<input type="checkbox"/>	
Windshield Wipers	Very Good			<input type="checkbox"/>	
Heater	Good			<input type="checkbox"/>	
Interior Lights	Very Good			<input type="checkbox"/>	
Seat Cushion / Arm Rest	Fair - wore			<input type="checkbox"/>	
Floor Boards	Very Good			<input type="checkbox"/>	
EMS Panel / Warnings	Very Good			<input type="checkbox"/>	
Door Latches	Very Good			<input type="checkbox"/>	
Glass/Mirrors	Very Good - no damage			<input type="checkbox"/>	
Air Conditioner	Very Good			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
Current Parts Manual	No			<input type="checkbox"/>	
Current Safety Manual	Yes			<input type="checkbox"/>	
Current O&MM	Yes			<input type="checkbox"/>	
Seat Belt	Yes			<input type="checkbox"/>	
Back Up Alarm	Yes			<input type="checkbox"/>	
ROPS Certification Plate	Yes			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
Fuel Level	85 percent			<input type="checkbox"/>	

ENGINE

	Condition - Remarks	Parts	Labor	Approved?	Photos
Oil Leaks	No			<input type="checkbox"/>	
Blow By	No			<input type="checkbox"/>	
Knocking	No			<input type="checkbox"/>	
Compression in Radiator	No			<input type="checkbox"/>	
Water in Oil	No			<input type="checkbox"/>	
Fluid Levels OK?	Yes			<input type="checkbox"/>	
EPA Decal	Yes			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
Anti-Freeze Color	red			<input type="checkbox"/>	
Oil Pressure (H/L/N)	Normal			<input type="checkbox"/>	
Smoke (B/D/L/W)	None			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
Operating Condition	Good			<input type="checkbox"/>	
Turbocharger / Blower	Good - Reman			<input type="checkbox"/>	
Fuel Injection System	Good - oil leak, collecting dust			<input type="checkbox"/>	
Governor	Good			<input type="checkbox"/>	
Engine Supports	Good			<input type="checkbox"/>	
Air Cleaners	Fair - Dirty			<input type="checkbox"/>	
Exhaust / Muffler	Good			<input type="checkbox"/>	
Oil Filter Condition (CUT)	Good			<input type="checkbox"/>	

Belts / Pulleys	Fair - some wear			<input type="checkbox"/>	
-----------------	------------------	--	--	--------------------------	--

COOLING SYSTEM

	Condition - Remarks	Parts	Labor	Approved?	Photos
Radiator	Good			<input type="checkbox"/>	
Coolers	Good			<input type="checkbox"/>	
Hoses	Good			<input type="checkbox"/>	
Water Pump	Good			<input type="checkbox"/>	
Fan	Good			<input type="checkbox"/>	
Fan Drive	Good			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
Leaks	No			<input type="checkbox"/>	

ELECTRICAL, STARTING AND CHARGING SYSTEM

	Condition - Remarks	Parts	Labor	Approved?	Photos
Batteries / Cables	Good			<input type="checkbox"/>	
Starter	Good			<input type="checkbox"/>	
Alternator	Good			<input type="checkbox"/>	
Wiring	Good			<input type="checkbox"/>	
Pre-Heater	Good			<input type="checkbox"/>	
Lighting	Good			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
Ether Aid	Yes			<input type="checkbox"/>	
Block Heater	Yes			<input type="checkbox"/>	

TRANSMISSION

	Condition - Remarks	Parts	Labor	Approved?	Photos
Transmission - Type	Good - checked 500 hours ago			<input type="checkbox"/>	
Case	Good			<input type="checkbox"/>	
Controls	New - Put in new ECM 50 hours ago			<input type="checkbox"/>	
Seals	Good			<input type="checkbox"/>	
Torque Converter	Good			<input type="checkbox"/>	
Universal Joints	Good			<input type="checkbox"/>	
Lines / Fittings	Fair - Front right side of tranny has oil leak. All new lines this winter			<input type="checkbox"/>	
Transmission - Reverse Shifts	Good			<input type="checkbox"/>	
Pump	Good			<input type="checkbox"/>	
Oil Filter Condition (CUT)	Good			<input type="checkbox"/>	
Operating Condition	Good			<input type="checkbox"/>	
Transmission - Forward Shifts	Good			<input type="checkbox"/>	
Cooler	Good			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
Transmission - Noisy	No			<input type="checkbox"/>	
Leaks	Yes - small leak on front right-wet			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
Transmission Type	powershift			<input type="checkbox"/>	

.STEERING.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Front Axle	Good			<input type="checkbox"/>	
Steering Linkage	Good			<input type="checkbox"/>	
Steering Gear Box	Good			<input type="checkbox"/>	
Tie Rods / Rod Ends	Good			<input type="checkbox"/>	
Articulate P & B	Good			<input type="checkbox"/>	
Steering Valves / Pumps	Good			<input type="checkbox"/>	
Steering Cylinder	Good			<input type="checkbox"/>	
Oil Lines	Fair - 2 lines with slight damage on front axle			<input type="checkbox"/>	
King Pins	Good			<input type="checkbox"/>	
Wheel Lean Cylinder	Good			<input type="checkbox"/>	
Supplemental Steer	Good			<input type="checkbox"/>	

.BRAKE.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Type (Pedal, Lever)	Good			<input type="checkbox"/>	
Type (Wet, Dry)	Good			<input type="checkbox"/>	
Control Valve	Good			<input type="checkbox"/>	
Lines	Good			<input type="checkbox"/>	
Master Cylinder	Good			<input type="checkbox"/>	
Compressor	Good			<input type="checkbox"/>	

Brake Linkage	Good			<input type="checkbox"/>	
Accumulators	Good			<input type="checkbox"/>	
Parking Brake	Good			<input type="checkbox"/>	
Hydraulic Pump	Good			<input type="checkbox"/>	
Hydraulic Cooler	Good			<input type="checkbox"/>	
Hydraulic Filter Condition	Good			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
Leaks	No			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
Holding What Gear?	2			<input type="checkbox"/>	

.TANDEMS.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Tandems	Good - right side collecting dust			<input type="checkbox"/>	
Wheel Lugs & Rims	Good - rims and tires not going with this machine. customer putting these on his new grader			<input type="checkbox"/>	
Differential	Good			<input type="checkbox"/>	
Differential Lock	Good			<input type="checkbox"/>	

.HYDRAULICS.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Overall Operating Condition	Good			<input type="checkbox"/>	
Tank	Good			<input type="checkbox"/>	
Pumps & Valves	Good			<input type="checkbox"/>	
Hose Lines	Good			<input type="checkbox"/>	

Linkage	Good			<input type="checkbox"/>	
Side Shift Cylinder	Good			<input type="checkbox"/>	
Lift Cylinders	Good			<input type="checkbox"/>	
Tip Cylinder	Good			<input type="checkbox"/>	
Wheel Lean Cylinder	Good			<input type="checkbox"/>	
Turn Drive Box	Good - No leaks			<input type="checkbox"/>	
Circle, Shoes & Plates	Good			<input type="checkbox"/>	
Circle A Frame	Good - tight			<input type="checkbox"/>	
Circle Side Shift Cylinder	Good			<input type="checkbox"/>	
Drive Line	Good			<input type="checkbox"/>	
Filter Condition (CUT)	Good			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
Leaks	No			<input type="checkbox"/>	

.BLADE.

	Condition - Remarks	Parts	Labor	Approved?	Photos
Face / Moldboard	Very Good			<input type="checkbox"/>	
Cutting Edge Condition	New			<input type="checkbox"/>	
Circle	Good - Reshimmed this winter			<input type="checkbox"/>	
A-Frame	Very Good			<input type="checkbox"/>	
Notes	14 foot				

.TIRES.

Notes	Tires will be swapped out on put on customer's new machine.				
	Condition - Remarks	Parts	Labor	Approved?	Photos
Spare	No			<input type="checkbox"/>	
	Condition - Remarks	Parts	Labor	Approved?	Photos
Number of Chains	none			<input type="checkbox"/>	

.COMMENTS, MISC. REPAIRS, GENERAL REMARKS.

	Parts	Labor	Approved?	Photos
Ripper will be added to new machine. Lines and brackets will stay with this machine.			<input type="checkbox"/>	

Marketing Photos

