2005 CATERPILLAR 143H	<b>Customer Owned Certified</b>		
MOTOR GRADERS			
Inspection Number:	Serial #:	APN00715	
Date Created:	Engine Serial #:	3PD14419	
Last Updated:	Transmission Serial #:	HSN00999	
Originated By:	SMU/Hrs:	12153	
Inspector:	Last Scheduled Oil Sample:	N/A	
Reviewer:	Last Cat Track System Inspection:	N/A	
Salesman:	Last Preventative Maintenance:	N/A	
Location:	Recommendation:	no recommendation	
Asking Price:	Final Price:	N/A	

## Features

■ EROPS

AIR CONDITIONER

■ DIFF LOCK/UNLOC

ALL WHEEL DRIVE

SPECIFICATIONS

■ ENGINE ENCLOSURES

■ LIGHTING

■ BEACON

AM FM RADIO

## Condition

— GENERAL	APPEARANCE -	

	Condition - Remarks	Parts	Labor	Approved?	Photos
Radiator Grill & Shroud	Good				
Eng. Enclose Hood / Stack	Good				
Fuel Tank	Good				
Crankcase Guard / Battery Box	Good				
Front Frame	Good				
Rear Frame	Good				
Counterweight	Good				
Pre-Cleaner Bowl	Good				
Cab or Canopy	Good				
Steps / Ladder	Fair				(1)
Grab Irons	Good				
	SE C				

Paint	Good				
Sheet Metal	Good				
	Condition - Remarks	Parts	Labor	Approved?	Photos
S.O.S. Taken	No				
		1000000	-		
	Condition - Remarks	Parts	Labor	Approved?	Photos
Safety Decals In Place	Yes				
Safety Decals Legible	Yes				
Rotating Beacon	No - Did not work				
Signal Lights	Yes				
ROPS	Yes		(20)		
Warning Lights	No - Left blinker did not work				
	Condition - Remarks	Parts	Labor	Approved?	Photos
Horn	Poor - Did not work				
	GAUGES, OPERATOR STATIO	N, CONSOLE -			
	Condition - Remarks	Parts	Labor	Approved?	Photos
Dash Console	Good				2
Gauges	Good				
Switches	Good				
Windshield Wipers	Good				
Heater	Good				
Interior Lights	Good				
Seat Cushion / Arm Rest	Good				
Tilli Tioot					1
Floor Boards	Good	2000			
	Good Good				
Floor Boards EMS Panel /					
Floor Boards  EMS Panel / Warnings	Good				

	Condition - Remarks	Parts	Labor	Approved?	Photos
Seat Belt	Yes		0.000.0000		
Back Up Alarm	No - Did not work				
	ENGINE				
	Condition - Remarks	Parts	Labor	Approved?	Photos
Oil Leaks	No				
Blow By	No				
Knocking	No				
Compression in Radiator	No				
Water in Oil	No				
Fluid Levels OK?	Yes				
	Condition - Remarks	Parts	Labor	Approved?	Photo
Operating Condition	Good	ruito	Lucoi		
Turbocharger / Blower	Good				
Fuel Injection System	Good				
Governor	Good				
Engine Supports	Good				
Air Cleaners	Good				
Exhaust / Muffler	Good				
_	COOLING SYSTE	м ———			
	Condition - Remarks	Parts	Labor	Approved?	Photo
Radiator	Good				
Coolers	Good				
Hoses	Good				
Water Pump	Good		3		
Fan	Good				
Fan Drive	Good				
	Condition - Remarks	Parts	Labor	Approved?	Photo

	Condition - Remarks	Parts	Labor	Approved?Pho
Batteries / Cables	Good			
Starter	Good			
Alternator	Good			
Wiring	Good			
Pre-Heater	Good			
Lighting	Good			
	Condition - Remarks	Parts	Labor	Approved?Pho
Ether Aid	Yes			
Block Heater	Yes			
	TRANSMISSION			
	Condition - Remarks	Parts	Labor	Approved?Pho
Transmission - Type	Good			
Case	Good			
Controls	Good			
Seals	Good			
Torque Converter	Good			
Universal Joints	Good			
Lines / Fittings	Good			
Transmission - Reverse Shifts	Good			
Pump	Good			
Operating Condition	Good		3	
Transmission - Forward Shifts	Good		H1270	
Cooler	Good		*	
	Condition - Remarks	Parts	Labor	Approved?Pho
		rarus	ranor	h-phiosea thruc
Transmission - Noisy	No			

	Condition - Remarks	Parts	Labor	Approved?	Photos
Type (Pedal, Lever)	Good				
Control Valve	Good				
Lines	Good				
Master Cylinder	Good				
Compressor	Good				
Brake Linkage	Good				
Accumulators	Good				
Parking Brake	Good				
Hydraulic Pump	Good				
Hydraulic Cooler	Good				
	Condition - Remarks	Parts	Labor	Approved?	Photo
Leaks	No				

- TANDEMS -

Condition - Remarks

Good

Good

Tandems

Wheel Lugs & Rims Labor Approved?Photos

Parts

Differential	Good			1	Ĩ	П	
Differential Lock	Good		1.1.4.1111				
	Victoria de la constanta de la		_				1
		RAULIC	· S				
	Condition - Remark	ks		Parts	Labor	Approved	?Photos
Overall Operating Condition	Good	-					
Tank	Good						
Pumps & Valves	Good		W. 25				
Hose Lines	Good						
Linkage	Good						
Side Shift Cylinder	Good						
Lift Cylinders	Good						
Tip Cylinder	Good						
Wheel Lean Cylinder	Good						
Turn Drive Box	Good						
Circle, Shoes & Plates	Good						
Circle A Frame	Good						
Circle Side Shift Cylinder	Good		P 6 (6) (1) (5 - 1) (6)				
Scar. Lift Arms & Gear Box	Good						
Ripper/Scar. Lift Cylinder	Good						
Drive Line	Good						
	Condition - Remar	ke		Parts	Labor	Approved	Dhoto-
Laska		<i>v</i> 9		Farts	Labor	1025071 151	FIIOLOS
Leaks	No						
	BLADE						
	Condition - Remar	ks		Parts	Labor	Approved	?Photos
Blade Size	14 ft.		Nico				
	<del></del> 7	TIRES -					
	Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section	Photos

Right Front	Bridgestone	32	No	No	No
Right Rear Center	Bridgestone	18	No	No	No
Right Rear	Bridgestone	18	No	No	No
Left Front	Bridgestone	32	No	No	No
Left Rear Center	Bridgestone	19	No	No	No
Left Rear	Bridgestone	18	No	No	No
Tire Size	17.5R25				

	Condition - Remarks	Parts	Labor	Approved? Photos
Spare	No			