

**SPECIFICATIONS**

**2000 CATERPILLAR 12HNA**

**Customer Owned Certified**

**MOTOR GRADERS**

<b>Inspection Number:</b>	<b>Serial #:</b>	4XM02346
<b>Date Created:</b>	<b>Engine Serial #:</b>	N/A
<b>Last Updated:</b>	<b>Transmission Serial #:</b>	N/A
<b>Originated By:</b>	<b>SMU/Hrs:</b>	13825
<b>Inspector:</b>	<b>Last Scheduled Oil Sample:</b>	N/A
<b>Reviewer:</b>	<b>Last Cat Track System Inspection:</b>	N/A
<b>Salesman:</b>	<b>Last Preventative Maintenance:</b>	N/A
<b>Location:</b>	<b>Recommendation:</b>	no recommendation
<b>Asking Price:</b>	<b>Final Price:</b>	N/A

**Client**

<b>Name:</b>	<b>City:</b>
<b>Client Id:</b>	<b>State:</b>
<b>Company:</b>	<b>Country:</b>

**Features**

- EROPS
- AIR CONDITIONER
- SIDE SHIFT
- DIFF LOCK/UNLOC
- ENGINE ENCLOSURES
- SLIPCLUTCH
- LIGHTING
- AM FM RADIO

**Condition**

**GENERAL APPEARANCE**

	Condition - Remarks	Parts	Labor	Approved?	Photos
<b>Radiator Grill &amp; Shroud</b>	Good - Small dent right left corner of radiator grill.			<input type="checkbox"/>	
<b>Paint</b>	Fair - Normal fading and scratches. No major just or damage.			<input type="checkbox"/>	

	Condition - Remarks	Parts	Labor	Approved?	Photos
<b>S.O.S. Taken</b>	No			<input type="checkbox"/>	
<b>Cleaning Required</b>	No			<input type="checkbox"/>	

**SAFETY ITEMS**

	Condition - Remarks	Parts	Labor	Approved?	Photos
<b>Signal Lights</b>	Yes			<input type="checkbox"/>	
<b>ROPS</b>	Yes				

				<input type="checkbox"/>	
Warning Lights	Yes			<input type="checkbox"/>	

	Condition - Remarks	Parts	Labor	Approved?	Photos
Horn	Good			<input type="checkbox"/>	

**GAUGES, OPERATOR STATION, CONSOLE**

	Condition - Remarks	Parts	Labor	Approved?	Photos
Gauges	Good - Fuel gauge not reading accurately. Pegged past full.			<input type="checkbox"/>	
Seat Cushion / Arm Rest	Fair - Material worn and peeling on bottom cushion.			<input type="checkbox"/>	
Glass/Mirrors	Fair - Right front lower glass cracked.			<input type="checkbox"/>	

	Condition - Remarks	Parts	Labor	Approved?	Photos
Back Up Alarm	Yes - Non-functional.			<input type="checkbox"/>	

**ENGINE**

	Condition - Remarks	Parts	Labor	Approved?	Photos
Oil Leaks	Yes - Right front wet with oil. Fuel system wet with oil.			<input type="checkbox"/>	
Blow By	No - Normal levels for age and hours. Nothing major.			<input type="checkbox"/>	
Knocking	No			<input type="checkbox"/>	
Compression in Radiator	No			<input type="checkbox"/>	
Water in Oil	No			<input type="checkbox"/>	
Fluid Levels OK?	Yes			<input type="checkbox"/>	

	Condition - Remarks	Parts	Labor	Approved?	Photos
Anti-Freeze Color	green			<input type="checkbox"/>	

	Condition - Remarks	Parts	Labor	Approved?	Photos
Operating Condition	Good - Started and operated with no apparent discrepancies.			<input type="checkbox"/>	

**COOLING SYSTEM**

Notes	no apparent discrepancies.
-------	----------------------------

	Condition - Remarks	Parts	Labor	Approved?	Photos
Leaks	No			<input type="checkbox"/>	

**ELECTRICAL, STARTING AND CHARGING SYSTEM**

**Notes** | no apparent discrepancies.

	Condition - Remarks	Parts	Labor	Approved?	Photos
<b>Ether Aid</b>	Yes			<input type="checkbox"/>	
<b>Block Heater</b>	Yes			<input type="checkbox"/>	

**TRANSMISSION**

	Condition - Remarks	Parts	Labor	Approved?	Photos
<b>Transmission - Reverse Shifts</b>	Good			<input type="checkbox"/>	
<b>Operating Condition</b>	Good - operated with no apparent discrepancies.			<input type="checkbox"/>	
<b>Transmission - Forward Shifts</b>	Good			<input type="checkbox"/>	

	Condition - Remarks	Parts	Labor	Approved?	Photos
<b>Transmission - Noisy</b>	No			<input type="checkbox"/>	
<b>Leaks</b>	No			<input type="checkbox"/>	

**STEERING**

	Condition - Remarks	Parts	Labor	Approved?	Photos
<b>Articulate P &amp; B</b>	Fair			<input type="checkbox"/>	
<b>Notes</b>	No other apparent discrepancies.				

**BRAKE**

**Notes** | No apparent discrepancies.

	Condition - Remarks	Parts	Labor	Approved?	Photos
<b>Leaks</b>	No			<input type="checkbox"/>	

**TANDEMS**

	Condition - Remarks	Parts	Labor	Approved?	Photos
<b>Tandems</b>	Good - Tandem seals leaking. Nothing major.			<input type="checkbox"/>	

**HYDRAULICS**

	Condition - Remarks	Parts	Labor	Approved?	Photos
<b>Overall Operating Condition</b>	Good - operated with no apparent discrepancies.			<input type="checkbox"/>	
<b>Lift Cylinders</b>	Fair - Both cylinders leaking at rods. Lower knuckles loose.			<input type="checkbox"/>	
<b>Tip Cylinder</b>	Fair - wet at cylinder rod			<input type="checkbox"/>	

**BLADE**

	Condition - Remarks	Parts	Labor	Approved?	Photos
Blade Size	14'			<input type="checkbox"/>	

**TIRES**

	Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section	Photos
Right Front			20				
Right Rear Center			90				
Right Rear			20				
Left Front			20				
Left Rear Center			20				
Left Rear			20				
Tire Size	14.0						
Average Life Remaining	31						

**COMMENTS, MISC. REPAIRS, GENERAL REMARKS**

	Parts	Labor	Approved?	Photos
Well maintained with no signs of abuse or misuse.			<input type="checkbox"/>	
Repairs have been made as needed. nice machine for age and hours.			<input type="checkbox"/>	