

1994 CATERPILLAR
214BFT
WHEEL EXCAVATOR

SALES INFORMATION

Catalog #	4573708	Stock #	202U015
Serial #	9MF00499	SMU / Hours	14,974
Availability	Available	Location	

FEATURES

- AM FM RADIO
 - BOOM, 1 PIECE
 - LIGHTING
- AUXILIARY HYDRAULICS
 - COUPLER, SWINGER
 - STABILIZER
- BEACON
 - HIGH PRESSURE HYDRAULICS ONE WAY

CONDITION

●●● Good ●● Fair ● Poor

GENERAL APPEARANCE

●●● Battery Box	●● Bottom Guarding Missing several panels	●●● Bumper
●● Cab or Canopy shows wear and age	●●● Cab Posts	●●● Car Body
●●● Counterweight	●● Decals faded - worn	●●● Draw Bar / Tie Downs
●●● Fenders / Skirt	●●● Fuel Tank	●●● Grab Irons
●●● Hood	●●● Main Frame Welds	●● Paint faded - some minor scratches and rust
●●● Platform	●●● Sheet Metal	●●● Side Doors
●● Steps / Ladder lower steps are slightly bent		
YES Cleaning Required?		

SAFETY ITEMS

●●● Beacon / Strobe	● Horn not working	●●● Safety Locks / Pins
● Seat Belt / Date	●●● Swing Brake	● Travel Alarm not working
YES Safety Decals In Place / Legible		

GAUGES, OPERATOR STATION, CONSOLE

●●● Dash Console	●● Door Latches / Seals seals missing	●● Floor Boards / Mats worn
●● Glass / Mirrors Right side glass cracked	●●● Headliner	●●● Heater
●●● Meter Replaced / Working	●● Operator Controls pilot valves seeping oil	● Seat Cushion / Arm Rest cloth torn - cushion deteriorated
●● Seat Suspension Type / Condition mechanical - some looseness	●●● Switches	● Windshield Wipers not working
NO Current O&MM	NO Current Parts Manual	NO Current Safety Manual

ENGINE

●●● Air Cleaners	●●● Anti-Freeze Color / Level	●●● Engine Supports
●●● Exhaust / Muffler / Stack	●●● Fuel Injection System	●●● Governor / Control
●● Oil Filter Condition / Service Hours	●●● Operating Condition	●●● Turbocharger / Blower
YES Blow By not excessive	NO Compression in Radiator	NO EPA Decal Legible
YES Fluid Levels OK?	NO Knocking	YES Oil Leaks rear seal / flywheel housing wet with oil, oil pan seeping - oil filter base leaking
NO Pre Lube System	NO Water in Oil	
Oil Pressure (H/L/N) Normal	Smoke Color (B/D/L/W) Normal	

COOLING SYSTEM

●●● Belts / Pulleys	●●● Coolers	●●● Fan
●● Hoses Heater hoses seeping	●●● Radiator	●●● Shroud / Guards
●●● Water Pump		

ELECTRICAL, STARTING AND CHARGING SYSTEM

●●● Alternator	●●● Batteries / Cables	●●● Electrical Battery Box
●●● Starter	●●● Wiring	●●● Work Lights
YES Rotating Beacon	YES Signal Lights Right front broke	

STEERING

●●● Front Axle - STEERING	●●● Hand Metering Unit	●●● Lines / Fittings - STEERING
●●● Steering Column / Tilt	●●● Steering Cylinder	●●● Steering Linkage
●●● Steering Operating Condition	●●● Steering Wheel	●●● Tie Rods / Rod Ends

HYDRAULICS

●● Boom Cylinder Drifts 2-3 inches when the function is stoped then drifts slowly	●● Bucket Cylinder conection block and hose seeping oil	●●● Control Linkage
--	---	---------------------

- Hose Lines
several are seeping at the crimps
- Rotex
Seeping from the swivel valve

- Out Rigger Cylinder
guards are bent
- Stick Cylinder
leaking

- Pumps & Valves
main valve is leaking from several areas
- Swing Gear
some wear / movement in the gear mesh

BOOM & STICK

- Boom & Stick
no visible cracks or damage
- Pins & Bushings
wear / movement in all joints

- Boom & Stick Pins
worn, loose

- Cylinder Pins
worn

Notes - BOOM & STICK
16'10" boom - 9' 10" stick

BUCKET

- Bucket Bottom
- Bucket Sides

- Bucket Linkage
very loose
- Cutting Edges
worn 25% remaining

- Bucket Mounts

Notes - BUCKET
60" spade bucket - rotating coupler
installed - very loose, hoses leaking

FINAL DRIVES

- Axle
- Housings

- Axle Bolts
- Planetaries / Diff

- Axle Housing
- Wheel Lugs & Rims

Notes - FINAL DRIVES
no leaks or noises

TIRES

	Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Left Front	Firestone		80	NO	NO	NO
Left Rear	Firestone		80	NO	NO	NO
Right Front	Firestone		50	NO	NO	NO
Right Rear	Firestone		50	NO	NO	NO

Tire Size - TIRES
445/65D19.5

COMMENTS, MISC. REPAIRS, GENERAL REMARKS

comment 1	comment 2
Inspected 10/31/19 @ 14,974 SHM	sell as is or auction